

# **Vehicle Condition Report**

#### Brasher's Portland Auto Auction

23585 NE Sandy Blvd. Wood Village, OR 97060 (503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

Vehicle Description								
2006 Dodge Dakota 4WD V6 Quad Cab 4WD ST 3.7L								
VIN	1D7HW28K56S657091							
Ext. Color	Silver							
Int. Color	Gray	Interior	Cloth					
Mileage	73,514 Actual Miles							
Engine	3.7L 6-Cylinder Gas							
Transmission	Auto w/Overdrive							



	Auction Data		Declarations				
Sale Date	To Be Announced	Warranty	GSA Regular Terms				
Run#	To Be Announced Inv # 9099	Mileage	73,514 Actual Miles				
Consignor	GSA FLEET SERVICES	Title	Clear Title				

#### Equipment

- 4 Wheel Drive
- Electronic Traction Control
- Camper Shell
- Tilt Steering Wheel
- Towing Package
- Power Brakes

- · Automatic w/ Overdrive
- Power Windows
- Cruise Control
- Steel Wheels
- Hard Top
- Electric Mirrors

- · 6 Cylinder Gas
- Power Locks
- Dual Air Bag
- AM/FM CD
- Tinted Windows
- Air Conditioning
- Trip Counter
- · Anti Lock Brakes
- Trailer Hitch
- Power Steering

			Damage	Descriptions (CR	completed on	4/1/2015 b	y Ryan Hea	ath)		
	#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
Front	1	Hood	Chipped	Multiple Instances						 
				Front Subtotal						
Interior	. 2	Carpets	Dirty	Multiple Instances						 

**VIN:** 1D7HW28K56S657091

**Inv#:** 9099

# Location 3 Interior	Action				hours	hours	hours	
	Dirty	Multiple Instances			Hours	110413	Hours	
4 Seats	Dirty	Multiple Instances						
Moldy								
5 Seats	Hole(S)	Other						
		Interior Subtotal			 	 		
6 Left Front Door	Scratched	Multiple Instances						
7 Left Front Fender	Scratched	Multiple Instances						
8 Left Qtr Panel	Scratched	Multiple Instances						
		Left Subtotal	-					
					-		-	
		N						
<b>9</b> Engine	Checked - Ok	None						
10 Transfer Case 4x4	Checked - Ok	None						
11 Transmission	Checked - Ok	None						
		Manhaniaal Ouktotal						
		Mechanical Subtotal		<del></del>	-	 	-	
12 Deck Lid	Scratched	Multiple Instances						
		Rear Subtotal						
							-	-
13 Right Front Door	Ding	1 To 2 Inches						
	.9	. 2300						
14 Right Front Fender	Ding	1 To 2 Inches						
	<ul><li>Seats</li><li>Left Front Door</li><li>Left Front Fender</li></ul>	5 Seats Hole(S)  6 Left Front Door Scratched  7 Left Front Fender Scratched  8 Left Qtr Panel Scratched  ical  9 Engine Checked - Ok  10 Transfer Case 4x4 Checked - Ok  11 Transmission Checked - Ok  12 Deck Lid Scratched	Interior Subtotal  Left Front Door Scratched Multiple Instances  Left Front Fender Scratched Multiple Instances  Left Qtr Panel Scratched Multiple Instances  Left Subtotal  Left Subtotal  Transfer Case 4x4 Checked - Ok None  Mechanical Subtotal  Left Subtotal  Rear Subtotal	Interior Subtotal  Left Front Door Scratched Multiple Instances  Left Qtr Panel Scratched Multiple Instances  Left Subtotal  Checked - Ok None  Transfer Case 4x4 Checked - Ok None  Mechanical Subtotal  Mechanical Subtotal  Rear Subtotal  Rear Subtotal   Ray Sight Front Door Ding 1 To 2 Inches	Interior Subtotal  Interior Subt	Interior Subtotal  Interior Subt	Interior Subtotal  Interior Subt	Interior Subtotal

**VIN:** 1D7HW28K56S657091 **Inv#:** 9099

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
15	Right Qtr Panel	Scratched	Multiple Instances						
			Right Subtotal						
Structural									
16	Frame	Checked - Ok	None						
			Structural Subtotal						
			Tatal						
			Total	-		-	-		

Tires						
Region	Brand	Size	Tread Depth			
Left Front	MATCHED	/-	Average (Average)			
Left Rear	MATCHED	/-	Average (Average)			
Right Front	MATCHED	/-	Average (Average)			
Right Rear	MATCHED	/-	Average (Average)			

### Miscellaneous

Interior odor OK

#### **Images**







VIN: 1D7HW28K56S657091 Inv#: 9099























**VIN:** 1D7HW28K56S657091 **Inv#:** 9099















